

Debugging Stand-Alone Real-Time Clock/Calendar-Based Applications

*Author: Alexandru Valeanu
Microchip Technology Inc.*

This application note describes how to debug an application using Microchip's MCP794XX and MCP795XX RTCC devices.

Several code examples are detailed and explained in [Table 1](#).

INTRODUCTION

An increasing number of applications require Real-Time Clock/Calendar (RTCC) devices.

Microchip's RTCC's (I²C™ and SPI) are feature-rich devices that incorporate EEPROM, Time/Date registers, Time-Stamp registers, alarm modules, SRAM, a watchdog timer, and event detect modules, making them useful in many timekeeping applications.

COMMON ISSUES

TABLE 1: COMMON ISSUES

Problem	Solution
The oscillator does not function	Take into account two main factors: hardware and firmware.
	Hardware
	<ul style="list-style-type: none"> Verify that you have the correct type and value of crystal. Every type of crystal has specific parameters such as: CLOAD (equivalent capacitance of the crystal); ESR (equivalent series resistor of the crystal, at the resonance frequency). Verify that you have the correct values of the capacitors, as stated in the crystal manufacturer's data sheet and/or in Microchip's documents. Make sure the board is clean. Some of the flux used in the Pb-free may be slightly conductive; leaving residue on the board will delay the oscillator from starting or prevent oscillation completely (a dirty board will create parasitic resistors and capacitors). Verify your layout for the oscillator. An example is described in AN1365, "Recommended Usage of Microchip Serial RTCC Devices". Ensure that the crystal was not overheated during soldering.
	Firmware
	<ul style="list-style-type: none"> Make sure the Start bit (ST) in register 00h is set; Set ST = 1 to enable the oscillator. Check if the EXTOSC bit in the Control register (addr 07h) is clear; EXTOSC = 0. This should be cleared when using an external crystal.
The oscillator occasionally starts and stops	If the oscillator starts and stops, it means that the Start bit is set. Take into account only the hardware issues described above (crystal, capacitors, board, layout). Additionally, moisture on the board can affect crystal operation, as can trying to measure the crystal using a standard (x1 or x10) oscilloscope probe.
The SRAM is losing data and the clock is resetting when VCC is removed	Make sure that you have enabled battery backup in the code, through the VBATEN bit in register 03h; VBATEN = 1. Measure the backup supply voltage to make sure it is within the specification given in the data sheet.

TABLE 1: COMMON ISSUES (CONTINUED)

Problem	Solution
<p>Cannot communicate with the I²C™ device (or does not acknowledge)</p>	<ul style="list-style-type: none"> • Make sure that RTCC is powered and VCC > VTRIP. • Verify the I²C bus is pulled high when inactive/idle.. • Ensure that you have the correct value pull-up resistors, refer to AN1028, “Recommended Usage of Microchip I²C™ Serial EEPROM Devices”. • Is the I²C bus address correct for the MCP794XX? <ul style="list-style-type: none"> - Nonvolatile (EEPROM): 0xAE (for writes), 0xAF (for reads). - Volatile (SRAM): 0xDE (for writes), 0xDF (for reads). • Is the address of the byte location correct? Entering an address past 0x5F for an SRAM operation will result in the MCP7941X not acknowledging the address. Addressing undefined EEPROM locations will result in the MCP7941X not acknowledging the address. • Have you installed the battery? If your application does not need a battery, the VBAT pin should be connected to ground.
<p>MFP does not toggle (MCP7941X)</p>	<p>Please consider two possible factors:</p> <p>Hardware</p> <p>MFP is an open-drain pin and needs a pull-up resistor. Verify that you have the correct resistor and the pin is high at power-up.</p> <p>Firmware</p> <p>MFP may be used as clockout (in timekeeping applications) or as interrupt (in alarm applications). The MFP pin can also be driven via the OUT bit. Ensure that this bit is not being modified by the code.</p> <p>In timekeeping applications (such as an electronic watch), MFP can output pulses to offer a time reference.</p> <p>An example of how to program the Control register (07h) for such an application is described in the code of AN1355, “A Complete Electronic Watch Based on MCP79410 I²C™ RTCC” (the code will toggle MFP at 1 Hz).</p> <p><code>rtcc_wr(SQWE + ALM_NONE + MFP_1HZ, ADDR_CTRL)</code>, where constants are defined as below:</p> <pre>#define ADDR_CTRL 0x07 // address of the control register #define SQWE 0x40 // MFP = square wave #define ALM_NONE 0x00 // no alarms activated #define MFP_1HZ 0x00 // MFP = square wave at 1 Hz</pre> <p>In alarm applications, the initialization code could be (example from AN1364):</p> <pre>rtcc_wr(ALM_0, ADDR_CTRL) ;// enable ALARM0, OUT=0, no SQWAVE rtcc_wr(ALMx_POL+ALMxC_ALL+MONDAY, ADDR_ALMOCTL) ;// MFP=1 on ALARM, match on all vars, ;// (alarm) day of week for alarm = 1</pre> <p>Definitions of constants for this example are:</p> <pre>#define ALM_0 0x10 // ALARM0 is activated (ADDR_CTRL) #define ALMx_POL 0x80 // polarity of MFP alarm (ADDR_ALMxCTL) #define ALMxC_ALL 0x70 // ALARM compare on all param (ADDR_ALMxCTL) #define ADDR_ALMOCTL 0x0d // address of ALARM0 CONTROL register</pre>
<p>Alarms do not trigger (MCP7941X)</p>	<p>Same issues that may effect MFP apply:</p> <ul style="list-style-type: none"> • MFP is open-drain and needs a pull-up. • The initialization code for an alarm application includes the two above statements related to Control register (07h) and ALARM0 Control register (0Dh).

TABLE 1: COMMON ISSUES (CONTINUED)

Problem	Solution
An alarm cannot be retrIGGERED	<p>The alarm interrupt flag, ALMxIF (bit 3 in the Alarm Control registers), is set automatically by the hardware but must be cleared in firmware in order to retrigger the alarm.</p> <p>The previous examples of code show the correct procedure, too. After every alarm match, re-initialize the alarm module, this is done by clearing the Alarm Interrupt Flag (ALMxIF).</p>
Cannot read the SPI device (MCP9752X)	<p>A read from an SPI device needs the master to produce the SPI clock. The clock generator is started only when writing a byte in the SPI data buffer. Accordingly, before reading the SPI device, write a byte in the SPI data buffer of the master. A generic example of code for a PIC18 application (including the SPI RTCC) could be:</p> <pre data-bbox="576 604 1446 861"> unsigned char spi_rdtype (void) { // READ A BYTE FROM THE SPI RTCC unsigned char aux ; // auxiliary variable SSP1BUF = 0x55 ; // start ck generator, writing a dummy byte // you may write any value in the range // 00h - FFh while (!PIR1bits.SSP1IF) ; // polling the SPI interrupt flag aux=SSP1BUF ; // temporary variable to store the received // value PIR1bits.SSP1IF = 0 ; // clear the interrupt flag after end of // reception return aux ; // return the SPI received value </pre>
Time is not accurate	<p>This is the most common issue in timekeeping applications. Inaccurate timekeeping can be caused by three factors: the 32,768 Hz crystal, the two external capacitors and the thermal drift of the crystal. There are two methods to solve the problem:</p> <ul data-bbox="576 1024 1446 1144" style="list-style-type: none"> • A good choice/match of the two capacitors (which can solve the problem of the offset of the frequency). Take into account the crystal tolerance. • The calibration register of the RTCC, which can compensate the two deviations of the frequency: offset and thermal drift. <p>The order of operations should be:</p> <ul data-bbox="576 1186 1446 1579" style="list-style-type: none"> • Match the capacitors to the chosen crystal; • Only after completing this, compensate the remaining offset through the calibration register; • The best tool to measure the frequency is an (expensive) high precision counter/frequency-meter. Due to the low-power operation of the oscillator, this cannot be tested with an oscilloscope probe without affecting the operation. The 32.768 kHz clock can also be observed as a square wave by enabling the CLKOUT. • Tolerance of crystals. • Crystal frequency varies with frequency. The system should be tested across all temperature and environmental conditions. • If the crystal is replaced with a device having equivalent parameters, the system should be re-qualified.

Common Crystal Issues

Please refer to AN1365, "Recommended Usage of Microchip Serial RTCC Devices" (DS01365).

CONCLUSION

A number of application notes are available to assist in developing with the RTCC. These are available on the Microchip web site at www.microchip.com/rtcc.

For additional information, please refer to the following documents:

- AN1365 – *“Recommended Usage of Microchip Serial RTCC Devices”*
- AN1364 – *“Using the Alarm Feature on the MCP79410 RTCC to Implement a Delayed Alarm”*
- AN1355 – *“A Complete Electronic Watch Based on MCP79410 I²C™ RTCC”*
- AN1413 – *“Temperature Compensation of a Tuning Fork Crystal Based on MCP79410”*
- TB3065 – *“Enabling Intelligent Automation Using the MCP7941X I²C™ RTCC”*
- AN1379 – *“Stopwatch Based on MCP79410 I²C™ RTCC”*
- AN1412 – *“How to Calculate UNIX® Time Using a PIC18 Microcontroller and the MCP795W20 SPI RTCC”*

APPENDIX A: REVISION HISTORY

Revision A (02/2013)

Initial Release.

AN1496

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rPIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MTP, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.


Analog-for-the-Digital Age, Application Maestro, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniclient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rFLAB, Select Mode, SQI, Serial Quad I/O, Total Endurance, TSHARC, UniWinDriver, WiperLock, ZENA and Z-Scale are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

GestIC and ULPP are registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2013, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 9781620770252

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949 ==

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC[®] MCUs and dsPIC[®] DSCs, KEELOQ[®] code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland
Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara
Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8569-7000
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing
Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hangzhou
Tel: 86-571-2819-3187
Fax: 86-571-2819-3189

China - Hong Kong SAR
Tel: 852-2943-5100
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8864-2200
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Osaka
Tel: 81-6-6152-7160
Fax: 81-6-6152-9310

Japan - Tokyo
Tel: 81-3-6880-3770
Fax: 81-3-6880-3771

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-5778-366
Fax: 886-3-5770-955

Taiwan - Kaohsiung
Tel: 886-7-213-7828
Fax: 886-7-330-9305

Taiwan - Taipei
Tel: 886-2-2508-8600
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820

11/29/12