

System Level Design Considerations When Using I²C™ Serial EEPROM Devices

*Author: Rick Stoneking
Microchip Technology Inc.*

INTRODUCTION

Developing systems that implement the I²C protocol for communicating with serial EEPROM devices requires that a certain key factors be considered during the hardware and software development phase if the system is to achieve maximum compatibility and robustness. This application note discusses these factors, both hardware and software, to help insure that an optimal system design is achieved. This application note is limited to single master systems and therefore does not specifically address the unique requirements of a multi-master system. However, the concepts presented in this application note apply equally as well to those systems.


CONDITIONS TO BE CONSIDERED

Due to the bi-directional nature of the data bus devices operate in both transmit and receive modes at various times. In order to make this bi-directional operation possible the protocol must define specific times at which any given device may transmit or receive, as well as define specific points in the protocol where the functions are swapped (i.e. the transmitter becomes the receiver and the receiver becomes the transmitter). There are a number of events which could potentially cause this sender/receiver 'synchronization' to be lost, which can result in situations where:

- Both the master and the slave are in a send mode.
- Both the master and the slave are in a receive mode.
- The 'bit count' is off by one or more bits between the master and the slave.

These events, which include the microcontroller being reset during I²C communication, brown-out conditions, excessive noise on the clock or data lines, and improper bus input levels during power up, can be effectively neutralized through a combination of hardware and software techniques.

FIGURE 1: RECOMMENDED HARDWARE CONFIGURATION



INSURING 'BUS-FREE' DURING POWER-UP

In order to insure that the internal state machine of the serial EEPROM is correctly initialized at power up, it is crucial to guarantee that the device sees a 'bus-free' condition (defined as both SCL and SDA being high) until $V_{DD_{min}}$ has been reached. The ideal way to guarantee this is through the use of pull-up resistors on both the SDA and SCL lines. In addition, these pull-ups should be tied to the same voltage source as the VDD pin of the device. In other words is the device VDD is supplied from the main positive supply rail then the SCL and SDA pull-ups should be connected to that same supply rail (as opposed to being connected to a microcontroller I/O pin, for example). Figure 1 is an example of the recommended hardware configuration. The reasoning behind doing this is the same for both adding the pull-up to the SCL line and for utilizing the same supply for the VDD pin and the pull-ups. As anyone who has had any experience with CMOS logic already knows, it is necessary to ensure that all inputs are tied either high or low, since allowing a CMOS input to float can lead to a number of problems. If the SCL line does not have a pull-up, or if the pull-ups are not tied to the VDD supply rail, then conditions occur, however briefly, where the SCL/SDA inputs are floating with respect to the VDD supply voltage. When possible this condition should be avoided.

When it is not possible to add a pullup resistor to the SCL line (i.e. the hardware design has already been finalized) then the firmware should be configured to either: 1) drive the SCL line high during power up or, 2) float the SCL input during power up.

Of these two options, the first is the recommended method, despite typical concerns regarding latch-up, because it does not negatively impact the battery life in battery powered applications. Microchip Technology's serial EEPROM devices, like all CMOS devices, are susceptible to latch-up, however latch-up does not occur until currents in excess of 100mA are injected into the pin. Typical microcontrollers are not capable of supply currents of this magnitude, therefore the risk of latch-up is extremely low.

The second option is also acceptable but does lead to a brief increase in the current draw of the device during the time period in which the SCL pin is floating with respect to VDD. This increase can be significant in comparison to the normal standby current of the device and can have a detrimental affect on battery life in power sensitive applications.

In all cases it is important that the SCL and SDA lines not be actively held low while the EEPROM device is powered up. This can have an indeterminable effect on the internal state machine and, in some cases, the state machine may fail to correctly initialize and the EEPROM will power up in an incorrect state.

Another improper practice which should be pointed out is the driving of the SDA line high by the microcontroller pin rather than tri-stating the pin and allowing the requisite pullup resistor to pull the bus up to the high state. While this practice would appear harmless enough, and indeed it is as long as the microcontroller and EEPROM device never get out of sync, there is a potential for a high current situation to occur. In the event that the microcontroller and EEPROM should get out of sync, and the EEPROM is outputting a 'low' (i.e. sending an ACK or driving a data bit of '0') while the microcontroller is driving a high then a low impedance path between VDD and VSS is created and excessive current will flow out of the microcontroller I/O pin and into the EEPROM SDA pin. The amount of current that flows is limited only by the IOL specification of the microcontroller's I/O pin. This high current state can obviously have a very detrimental effect on battery life, as well as potentially present long term reliability problems associated with the excess current flow.

FORCING INTERNAL RESET VIA SOFTWARE

In all designs it is recommended that a software reset sequence be sent to the EEPROM as part of the microcontrollers power up sequence. This sequence guarantees that the EEPROM is in a correct and known state. Assuming that the EEPROM has powered up into an incorrect state (or that a reset occurred at the microcontroller during communication), the following sequence (which is further explained below) should be sent in order to guarantee that the serial EEPROM device is properly reset:

- START Bit
- Clock in nine bits of '1'
- START Bit
- STOP Bit

The first START bit will cause the device to reset from a state in which it is expecting to receive data from the microcontroller. In this mode the device is monitoring the data bus in receive mode and can detect the START bit which forces an internal reset.

The nine bits of '1' are used to force a reset of those devices that could not be reset by the previous START bit. This occurs only if the device is in a mode where it is either driving an acknowledge on the bus (low), or is in an output mode and is driving a data bit of '0' out on the bus. In both of these cases the previous START bit (defined as SDA going low while SCL is high) could not be generated due to the device holding the bus low. By sending nine bits of '1' it is guaranteed that the device will see a NACK (microcontroller does not drive the bus low to acknowledge data sent by EEPROM) which also forces an internal reset.

The second START bit is sent to guard against the rare possibility of an erroneous write that could occur if the microcontroller was reset while sending a write command to the EEPROM, and, the EEPROM was driving an ACK on the bus when the first START bit was sent. In this special case if this second START bit was not sent, and instead the STOP bit was sent, the device could initiate a write cycle. This potential for an erroneous write occurs only in the event of the microcontroller being reset while sending a write command to the EEPROM.

The final STOP bit terminates bus activity and puts the EEPROM in standby mode.

This sequence does not effect any other I²C devices which may be on the bus as they will simply disregard it as an invalid command.

SUMMARY

This application note has presented ideas that are fundamental in nature, yet not always obvious, to the utilization of I²C serial EEPROM devices. Ideally the hardware/software engineer(s) takes these ideas into consideration during system development and design accordingly. It is recommended that the software reset sequence detailed in this application note be added to the system initialization code of any system that utilizes an I²C serial EEPROM device.

REFERENCES

- 'I²C-Bus Specification', Philips Semiconductors, January 1992
- 'The I²C-Bus and How to Use It', Philips Semiconductors, April 1995

NOTES:

Note the following details of the code protection feature on PICmicro® MCUs.

- The PICmicro family meets the specifications contained in the Microchip Data Sheet.
- Microchip believes that its family of PICmicro microcontrollers is one of the most secure products of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the PICmicro microcontroller in a manner outside the operating specifications contained in the data sheet. The person doing so may be engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable”.
- Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our product.

If you have any further questions about this matter, please contact the local sales office nearest to you.

Information contained in this publication regarding device applications and the like is intended through suggestion only and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. No representation or warranty is given and no liability is assumed by Microchip Technology Incorporated with respect to the accuracy or use of such information, or infringement of patents or other intellectual property rights arising from such use or otherwise. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, FilterLab, KEELOQ, microID, MPLAB, PIC, PICmicro, PICMASTER, PICSTART, PRO MATE, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


dsPIC, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, microPort, Migratable Memory, MPASM, MPLIB, MPLINK, MPSIM, MXDEV, PICC, PICDEM, PICDEM.net, rPIC, Select Mode and Total Endurance are trademarks of Microchip Technology Incorporated in the U.S.A.

Serialized Quick Turn Programming (SQTP) is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2002, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.



Microchip received QS-9000 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona in July 1999. The Company's quality system processes and procedures are QS-9000 compliant for its PICmicro® 8-bit MCUs, KEELOQ® code hopping devices, Serial EEPROMs and microperipheral products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office

2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200 Fax: 480-792-7277
Technical Support: 480-792-7627
Web Address: <http://www.microchip.com>

Rocky Mountain

2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7966 Fax: 480-792-7456

Atlanta

500 Sugar Mill Road, Suite 200B
Atlanta, GA 30350
Tel: 770-640-0034 Fax: 770-640-0307

Boston

2 Lan Drive, Suite 120
Westford, MA 01886
Tel: 978-692-3848 Fax: 978-692-3821

Chicago

333 Pierce Road, Suite 180
Itasca, IL 60143
Tel: 630-285-0071 Fax: 630-285-0075

Dallas

4570 Westgrove Drive, Suite 160
Addison, TX 75001
Tel: 972-818-7423 Fax: 972-818-2924

Detroit

Tri-Atria Office Building
32255 Northwestern Highway, Suite 190
Farmington Hills, MI 48334
Tel: 248-538-2250 Fax: 248-538-2260

Kokomo

2767 S. Albright Road
Kokomo, Indiana 46902
Tel: 765-864-8360 Fax: 765-864-8387

Los Angeles

18201 Von Karman, Suite 1090
Irvine, CA 92612
Tel: 949-263-1888 Fax: 949-263-1338

New York

150 Motor Parkway, Suite 202
Hauppauge, NY 11788
Tel: 631-273-5305 Fax: 631-273-5335

San Jose

Microchip Technology Inc.
2107 North First Street, Suite 590
San Jose, CA 95131
Tel: 408-436-7950 Fax: 408-436-7955

Toronto

6285 Northam Drive, Suite 108
Mississauga, Ontario L4V 1X5, Canada
Tel: 905-673-0699 Fax: 905-673-6509

ASIA/PACIFIC

Australia

Microchip Technology Australia Pty Ltd
Suite 22, 41 Rawson Street
Epping 2121, NSW
Australia
Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

China - Beijing

Microchip Technology Consulting (Shanghai)
Co., Ltd., Beijing Liaison Office
Unit 915
Bei Hai Wan Tai Bldg.
No. 6 Chaoyangmen Beidajie
Beijing, 100027, No. China
Tel: 86-10-85282100 Fax: 86-10-85282104

China - Chengdu

Microchip Technology Consulting (Shanghai)
Co., Ltd., Chengdu Liaison Office
Rm. 2401, 24th Floor,
Ming Xing Financial Tower
No. 88 TIDU Street
Chengdu 610016, China
Tel: 86-28-6766200 Fax: 86-28-6766599

China - Fuzhou

Microchip Technology Consulting (Shanghai)
Co., Ltd., Fuzhou Liaison Office
Unit 28F, World Trade Plaza
No. 71 Wusi Road
Fuzhou 350001, China
Tel: 86-591-7503506 Fax: 86-591-7503521

China - Shanghai

Microchip Technology Consulting (Shanghai)
Co., Ltd.
Room 701, Bldg. B
Far East International Plaza
No. 317 Xian Xia Road
Shanghai, 200051
Tel: 86-21-6275-5700 Fax: 86-21-6275-5060

China - Shenzhen

Microchip Technology Consulting (Shanghai)
Co., Ltd., Shenzhen Liaison Office
Rm. 1315, 13/F, Shenzhen Kerry Centre,
Renminnan Lu
Shenzhen 518001, China
Tel: 86-755-2350361 Fax: 86-755-2366086

Hong Kong

Microchip Technology Hongkong Ltd.
Unit 901-6, Tower 2, Metroplaza
223 Hing Fong Road
Kwai Fong, N.T., Hong Kong
Tel: 852-2401-1200 Fax: 852-2401-3431

India

Microchip Technology Inc.
India Liaison Office
Divyasree Chambers
1 Floor, Wing A (A3/A4)
No. 11, O'Shaugnessey Road
Bangalore, 560 025, India
Tel: 91-80-2290061 Fax: 91-80-2290062

Japan

Microchip Technology Japan K.K.
Benex S-1 6F
3-18-20, Shinyokohama
Kohoku-Ku, Yokohama-shi
Kanagawa, 222-0033, Japan
Tel: 81-45-471- 6166 Fax: 81-45-471-6122

Korea

Microchip Technology Korea
168-1, Youngbo Bldg. 3 Floor
Samsung-Dong, Kangnam-Ku
Seoul, Korea 135-882
Tel: 82-2-554-7200 Fax: 82-2-558-5934

Singapore

Microchip Technology Singapore Pte Ltd.
200 Middle Road
#07-02 Prime Centre
Singapore, 188980
Tel: 65-334-8870 Fax: 65-334-8850

Taiwan

Microchip Technology Taiwan
11F-3, No. 207
Tung Hua North Road
Taipei, 105, Taiwan
Tel: 886-2-2717-7175 Fax: 886-2-2545-0139

EUROPE

Denmark

Microchip Technology Nordic ApS
Regus Business Centre
Lautrup høj 1-3
Ballerup DK-2750 Denmark
Tel: 45 4420 9895 Fax: 45 4420 9910

France

Microchip Technology SARL
Parc d'Activite du Moulin de Massy
43 Rue du Saule Trapu
Batiment A - 1er Etage
91300 Massy, France
Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79

Germany

Microchip Technology GmbH
Gustav-Heinemann Ring 125
D-81739 Munich, Germany
Tel: 49-89-627-144 0 Fax: 49-89-627-144-44

Italy

Microchip Technology SRL
Centro Direzionale Colleoni
Palazzo Taurus 1 V. Le Colleoni 1
20041 Agrate Brianza
Milan, Italy
Tel: 39-039-65791-1 Fax: 39-039-6899883

United Kingdom

Arizona Microchip Technology Ltd.
505 Eskdale Road
Winnersh Triangle
Wokingham
Berkshire, England RG41 5TU
Tel: 44 118 921 5869 Fax: 44-118 921-5820